 Drainage System Feature	Defect or Problem	Condition When Maintenance is Needed	Results Expected When Maintenance is Performed
Sediment Storage area	Excessive Sediment Accumulation	Sediment accumulation within 36 inches of water surface.	Sediment removed.
Aqua Swirl Chamber	Trash and Floatable Debris Accumulation	Excessive trash and floatable debris accumulation swirl chamber.	Minimal trash or other floatable debris.
Manhole Cover	Cover Damaged/ Not Working	One maintenance person cannot remove lid after applying 80 pounds of lift, corrosion of deformation of cover.	Cover repaired to proper working specifications or replaced.
Structure	Vault Structure has Cracks in Wall, Bottom, and Damage to Frame and/or Top Slab	Cracks wider than one-half inch or evidence of soil particles entering the structure through the cracks, or maintenance/inspection personnel determine that the vault is not structurally sound.	Vault repaired or replaced so that vault meets design specifications and is structurally sound.
Structure	Vault Structure has Cracks at the Joint of any Inlet/ Outlet Pipe	Cracks wider than one-half inch at the joint of any inlet/outlet pipe or evidence of soil particles entering through the cracks.	Vault repaired so that no cracks exist wider than one-fourth inch at the joint of inlet/outlet pipe.
Baffles	Baffles	Baffles corroding, cracking, warping, and/or showing signs of failure as determined by maintenance/inspection person.	Baffles repaired or replaced to design specifications.

#27 – Maintenance Standards for Aqua Shield Aqua-Swirl: