#15 – Maintenance Standards for Baffle Oil/Water Separators (BMP OW.01) (American Petroleum Institute [API] Type):

V	Drainage System Feature	Defect or Problem	Condition When Maintenance is Needed	Results Expected When Maintenance is Performed
	Effluent Water Quality	Inspection of Discharge Water for Obvious Signs of Poor Water Quality	Floating oil in excess of 1 inch in first chamber, any oil in other chambers or effluent, or other contaminants of any type in any chamber.	No contaminants present other than a surface oil film. Effluent discharge from vault should be clear without thick visible sheen.
	Structure	Sediment Accumulation	Sediment depth in bottom of vault exceeds 6 inches in depth.	No sediment deposits on vault bottom that would impede flow through the vault and reduce separation efficiency.
	General	Trash and Debris Accumulation	Trash and debris accumulation in vault, or pipe inlet/outlet, floatable and non-floatable.	Trash and debris removed from vault, and inlet/outlet piping.
	General	Oil Accumulation	Oil accumulations that exceed 1 inch, at the surface of the water or 6 inches of sludge in the sump.	No visible oil depth on water. Extract oil/sludge from vault by vactoring. Disposal in accordance with state and local rules and regulations.
	Structure	Damaged Pipes	Inlet or outlet piping damaged or broken and in need of repair.	Pipe repaired or replaced.
	Structure	Access Cover Damaged/Not Working	Cover cannot be opened, corrosion/deformation of cover.	Cover repaired to proper working specifications or replaced.
	Structure	Vault Structure Damage Includes Cracks in Walls Bottom, Damage to Frame and/or Top Slab	Maintenance person judges that structure is unsound.	Vault replaced or repairs made so that vault meets design specifications and is structurally sound.
	Structure	Vault Structure Damage Includes Cracks in Walls Bottom, Damage to Frame and/or Top Slab	Cracks wider than one-half inch at the joint of any inlet/outlet pipe or evidence of soil particles entering through the cracks.	Vault repaired so that no cracks exist wider than one-fourth inch at the joint of the inlet/outlet pipe.
	Structure	Baffles	Baffles corroding, cracking, warping and/or showing signs of failure as determined by maintenance/inspection person.	Baffles repaired or replaced to specifications.

#15 – Maintenance Standards for Baffle Oil/Water Separators (BMP OW.01) (American Petroleum Institute [API] Type):

V	Drainage System Feature	Defect or Problem	Condition When Maintenance is Needed	Results Expected When Maintenance is Performed
	Structure	Access Ladder Damaged	Ladder is corroded or deteriorated, not functioning properly, not securely attached to structure wall, missing rungs, cracks, and misaligned.	Ladder replaced or repaired and meets specifications, and is safe to use as determined by inspection personnel.